

Inspection Report

Report No.: XYWD-140610
Supplier: XY-GLOBAL

Inspection Date: 3th July, 2014
Inspector: Leo

Inspection only for: PO: XYWD-140610 Item No. XY31SY30	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY30	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection:
No failure.

Dimension Inspection:
No failure, below measurement report for reference.

Assembly Test:
No failure

Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records:




1. Packing	2. Product																
																	
3. Product	4. Product																
	XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co., Ltd XYWD-140610 Inspection Report <table border="1"> <tr> <td>Product Name</td> <td>XY31SY30</td> <td>Inspection Date</td> <td>2014-07-03</td> </tr> <tr> <td>Product Type</td> <td>XY31SY30</td> <td>Inspector</td> <td>Leo</td> </tr> <tr> <td>Product Qty</td> <td>30000PCS</td> <td>Inspection Qty</td> <td>30000PCS</td> </tr> <tr> <td>Product Lot</td> <td>XY31SY30</td> <td>Inspection Result</td> <td>PASS</td> </tr> </table> Inspection Summary: The inspection sample plan is 100% inspection. Inspection Result: PASS Inspector: Leo	Product Name	XY31SY30	Inspection Date	2014-07-03	Product Type	XY31SY30	Inspector	Leo	Product Qty	30000PCS	Inspection Qty	30000PCS	Product Lot	XY31SY30	Inspection Result	PASS
Product Name	XY31SY30	Inspection Date	2014-07-03														
Product Type	XY31SY30	Inspector	Leo														
Product Qty	30000PCS	Inspection Qty	30000PCS														
Product Lot	XY31SY30	Inspection Result	PASS														
5. Product:	6. report																

[illegible]