XY-GLOBAL **XY Electronics Technology Co., Ltd**

Inspection Report

Report No.: XYL-150725 **Inspection Date:** 14th Sep, 2015
Supplier : XY-GLOBAL **Inspector:** Leo

Inspection only for:	Inspection Result:
PO . XYL-150725 Item No. XY11LM025	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM025	18000PCS	1% inspection	0pcs	No failure	18000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

5. Product:

6. Report:

□□	□□□ □□□□□□□□□□□□□□□□□□□□ □□□□□□□OEM□□□□□□□□□□ □□
□□	□ ADC12□A380□
□□□□	□□ □□□□□
□□□□	□ □□□□□□□□□□□□□□□□□□□ □□□□
□□	□ □□□□□□□□□□□
□□□□	CNC □□□□□□□□□□□□□ □□□□□□□□□□□□□□□□
□□□□	□□ □□□□□□□gague□□□□□□□□□□□□ □□□□□□□□□□□□□□□□□□□ □□□□□□□□□□□□□□□□□□□□□□□□□ □
MOQ	□□
□□/□□	+/-0.01□□
□□	T / T □□50□□□□50□T / T□□□;□□□□
□□□□	CNC □□□□□□□□□□□□□□□□□□□□□ □□□□□□□□□□□□□□□
□□	□□□ □□□□□□□□□□□□□□□□□ □□□□□□□□□□□□□□□
□□	□□□ □□
□□	20-25□ T / T 50□□□□□□
□□□□	□□ □□□□□

1.Name□ □□□OEM□□□□□□
2.Process□ □□□□□□□□□□□
3.□□□ □□□ADC12□A380□
4.□□□□□□ □□□□□□□□□□□□□□□□
5.Tolerance□ □□□□+/-0.01□□
6.□□ □□□100□□□
7.Specification□ OEM□□□□□□□□□□□□□□□□
8□ □□□□□□□25-30□□□□□□□
9□ □□□□□□□□□□□□□□□□ accessoried□□□□□□□
10□ □□□□□□□□□□Austrial□□□□□
11.□□□ ISO 9001
□□□□□
1□ □ISO□□□10□□□□
2□ □□□□□□
3□ sureface□□□□□kindls□abailable
4□ □□□□□□□□□□
5□ □□□□□
6□ □□□□
7□ □□□□□□□□□□□□□□
□□□□□
□ □□□□□□□□□□□
□ □□□□□□□□□□
□ □□□□□□ISO9001
□ □□□□□□□□□□□□□□
□ □□□OEM□□□

High qualified surface treatment can make your parts perfect !!!