

Inspection Report

Report No.: XYL-150806

Inspection Date:17th Sep, 2015

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYL-150806 Item No. XY11LM036	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM036	16000PCS	1% inspection	Opes	No failure	16000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure


Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

[illegible]

5. Product:

6. Report:

項目	項目詳細説明OEM項目詳細説明
項目	項目ADC12項目A380項目
項目	項目詳細説明
項目	項目詳細説明項目詳細説明
項目	項目詳細説明
項目	項目詳細説明項目詳細説明項目詳細説明項目
項目	項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目
項目	項目詳細説明
項目/項目	+/-0.01項目
項目	項目項目50項目項目項目項目項目50項目項目
項目	項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目
項目	項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目
項目	項目
項目	項目項目50項目項目25項目項目
項目	項目詳細説明項目詳細説明
1.項目項目詳細説明	
2.項目項目詳細説明項目詳細説明	
3.項目項目ADC12項目A380項目	
4.項目詳細説明項目詳細説明項目詳細説明項目	
5.項目項目±0.01項目	
6.項目項目100項目	
7.項目詳細説明項目詳細説明項目詳細説明項目	
8.項目項目25-30項目	
9.項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目	
10.項目詳細説明項目詳細説明項目詳細説明項目	
11.項目項目ISO 9001	
項目	
1.10項目項目ISO項目	
2.項目詳細説明項目詳細説明項目	
3.項目詳細説明項目詳細説明項目	
4.項目詳細説明項目	
5.項目	
6.項目	
7.項目詳細説明項目	
項目	
項目詳細説明項目詳細説明項目	
項目詳細説明項目	
項目項目ISO9001	
項目詳細説明項目詳細説明項目	
項目OEM項目詳細説明項目	

Safety is our serious job for our worker and engineer team

