

Inspection Report


Report No.: XYSL-150722
 Supplier : XY-GLOBAL

Inspection Date: 25th Aug, 2015
 Inspector: Leo

Inspection only for: PO . XYSL-150722 Item No. XY31XL042	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL042	13000PCS	1% inspection	0pcs	No failure	13000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

品名	CNC加工品
材質	AL6061 AL6065 AL6063 AI7075 SUS304 SUS303 SUS316
仕様	
公差	±0.01
MOQ	100個
納期	T/T 50% 前払い 50% 納品時
加工方法	CNC加工
表面処理	無処理
検査	20-25% T/T 50% 前払い
梱包	10個/箱
1. Name	OEM
2. 材質	CNC
3. 仕様	AL6061 AL6065 AL6063 AI7075 POM
4. 公差	±0.01
5. Tolerance	±0.01
6. MOQ	100個
7. Specification	OEM
8. 納期	25-30日
9. 加工方法	CNC加工
10. 表面処理	accessoried
11. 検査	ISO 9001
1. 仕様	ISO
2. 材質	
3. kinds	sureface available
4. 公差	
5. 納期	
6. 検査	
7. 加工方法	
8. 仕様	
9. 材質	ISO9001
10. 公差	
11. 加工方法	OEM

Safety is our serious job for our worker and engineer team

