

Inspection Report

Report No.: XYL-150815
Supplier : XY-GLOBAL

Inspection Date: 20th Sep, 2015
Inspector: Leo

Inspection only for: PO : XYL-150815 Item No. XY11LM045	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM045	16000PCS	1% inspection	0pcs	No failure	16000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

	OEM
	ADC12A380
	+/-0.01
	5050
	5025
1.	
2.	
3.ADC12A380	
4.	
5. ± 0.01	
6.100	
7.	
8.25-30	
9.	
10.	
11.ISO 9001	
1.10ISO	
2.	
3.	
4.	
5.	
6.	
7.	
ISO9001	
OEM	

Safety is our serious job for our worker and engineer team

