

Inspection Report

Report No.: XYL-150804
Supplier : XY-GLOBAL

Inspection Date: 17th Sep, 2015
Inspector: Leo

Inspection only for: PO . XYL-150804 Item No. XY11XL047	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11XL047	14000PCS	1% inspection	Opes	No failure	14000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

[illegible]

5. Product:

6. Report:

	OEM
	ADC12A380
	+/-0.01
	5050
	5025
1.	
2.	
3.ADC12A380	
4.	
5. ± 0.01	
6.100	
7.	
8.25-30	
9.	
10.	
11.ISO 9001	
1.10ISO	
2.	
3.	
4.	
5.	
6.	
7.	
ISO9001	
OEM	

High qualified surface treatment can make your parts perfect !!!

