



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYJ-131015

Supplier : XY-GLOBAL

Inspection Date: 9th Nov-, 2013

Inspector: LEO

Inspection only for:

PO : XYJ-131015 Item No. XY-CT-D-060

Inspection Result:

PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-CT-D-060	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing




2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

	CNC加工品
	AL6061 AL6065AL6063AL7075; SUS304SUS303SUS316
	CNC加工品
	gague
	+/-0.01
	T / T 50T / T
	T / T 5020-25 NBSP
1.Name	cnc
2.Process	
	AL6061 AL6065AL6063AL7075
4.	
5.Tolerance	±0.01
6.	100
7.Specification	serice
8.	25-30
9.	accessoried
10.	Austrial
11&NBSP;	ISO 9001
1	10ISO
2.	
3.	kindlsavailable
4.	
5.	
6.	
7.	
&NBSP;	
	ISO9001