

Inspection Report

Report No.: XYBA-140915
Supplier : XY-GLOBAL

Inspection Date:14th Oct-, 2014
Inspector:LEO

Inspection only for: PO . XYBA-140915 Item No. XY21ZC010	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC010	500PCS	7% inspection	0pcs	No failure	500pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :

XY21ZC010									
1	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
2	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
3	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
4	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
5	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
6	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
7	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
8	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
9	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
10	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
11	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
12	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
13	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
14	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
15	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
16	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
17	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
18	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
19	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
20	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
21	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
22	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
23	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
24	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
25	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
26	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
27	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
28	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
29	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
30	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
31	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
32	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
33	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
34	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
35	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
36	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
37	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
38	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
39	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
40	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
41	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
42	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
43	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
44	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
45	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
46	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
47	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
48	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
49	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000
50	40.000	0.000	0.000	40.000	0.000	0.000	0.000	0.000	0.000

6. Inspection report:

11

品名	铝合金CNC加工件CNC件
材料	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
规格	定制
数量	10000件
单位	件
用途	工业机械零件
表面处理	阳极氧化
交货期	15天
包装	纸箱
备注	+/-0.01mm
重量	50g
长度	50mm
直径	25mm
厚度	5mm

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100 [illegible]

8. 25-30

9. □□□□□□□□□□□□□□ □□□□□□□□□□□□

10.

11 □ □ □ □ □ □ □ □ ISO 9001

--	--	--	--	--

1.10 □□□□□ISO□□

2.

3. □□□□□□□□□□□□□□

4. □□□□□□□□

5.□□□□□

6.□□□□□□

7. □□□□□□□□□□

--	--	--	--	--

[illegible][illegible]

□□□□□□□□ ISO9001

[illegible]

☐ OEM	☐	☐	☐	☐	☐
------------------------------	--------------------------	--------------------------	--------------------------	--------------------------	--------------------------