

Inspection Report

Report No.: XYL-150808
Supplier : XY-GLOBAL

Inspection Date: 17th Sep, 2015
Inspector: Leo

Inspection only for: PO . XYL-150808 Item No. XY11LM038	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM038	16000PCS	1% inspection	Opes	No failure	16000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure	
------------	--

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

[illegible]

5. Product:

6. Report:

項目	顧客指定の仕様書に準拠し、OEMの承認を得る。
部材	ADC12/A380
寸法	標準品
公差	公差は図面に示す通りとする。
色	標準色（黒）
表面処理	表面処理は、必要に応じて別途指定を受ける。 塗装
包装	個装または箱装のいずれかを選択可能。
検査	全数検査を実施する。
不良率	不良率は0.1%以下と目標とする。
納期	標準納期は約5営業日であるが、急ぎの場合は別途相談可能。
ロット	最小ロットは50個であるが、少量発注も対応可能。
保証	品質保証期間は1年である。 欠陥発生時の交換・修理を保障する。
価格	価格は数量や仕様に依り変動する。 見積もりを別途提出する。
支払条件	前払金または代金引当による。
その他	詳細な仕様書と納入条件については、別途資料を参照してください。

1. 項目：顧客指定の仕様書に準拠し、OEMの承認を得る。

2. 部材：ADC12/A380

3. 公差：公差は図面に示す通りとする。

4. 色：標準色（黒）

5. 表面処理：表面処理は、必要に応じて別途指定を受ける。 塗装

6. 包装：個装または箱装のいずれかを選択可能。

7. 検査：全数検査を実施する。

8. 不良率：不良率は0.1%以下と目標とする。

9. 納期：標準納期は約5営業日であるが、急ぎの場合は別途相談可能。

10. ロット：最小ロットは50個であるが、少量発注も対応可能。

11. 保証：品質保証期間は1年である。 欠陥発生時の交換・修理を保障する。

12. 価格：価格は数量や仕様に依り変動する。 見積もりを別途提出する。

13. 支払条件：前払金または代金引当による。

14. その他：詳細な仕様書と納入条件については、別途資料を参照してください。

Safety is our serious job for our worker and engineer team

