

Inspection Report

Report No.: XYBA-141119
Supplier : XY-GLOBAL

Inspection Date: 19th Dec., 2014
Inspector:LEO

Inspection only for:	Inspection Result:
PO . XYBA-141119 Item No. XY21ZC038	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC038	5000Set	7% inspection	0pcs	No failure	6000Set

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :

XY21ZC038									
1	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
2	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
3	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
4	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
5	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
6	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
7	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
8	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
9	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
10	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
11	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
12	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
13	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
14	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
15	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
16	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
17	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
18	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
19	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
20	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
21	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
22	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
23	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
24	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
25	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
26	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
27	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
28	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
29	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
30	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
31	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
32	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
33	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
34	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
35	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
36	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
37	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
38	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
39	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
40	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
41	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
42	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
43	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
44	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
45	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
46	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
47	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
48	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
49	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
50	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00

6. Inspection report:

11

品名	铝合金CNC加工件CNC件
材料	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
规格	定制
数量	10000件
单位	件
重量	约100kg
尺寸	长100mm 宽50mm 高20mm
表面处理	阳极氧化 喷砂 电泳 电镀
包装	泡沫箱+气泡膜+木架
交货期	10个工作日
公差	±0.01mm
最小起订量	500件
最大起订量	50000件
付款方式	预付30% 货到付清
交货地点	工厂
联系人	王经理
电话	13800000000
地址	深圳市宝安区

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100

7.

8. 25-30

9. □□□□□□□□□□□□□□ □□□□□□□□□□□□

10.

11 □ □ □ □ □ □ □ □ ISO 9001

--	--	--	--	--

1.10 □□□□□ISO□□

2.

3. □□□□□□□□□□□□□□

4. □□□□□□□□

5.□□□□□

6.□□□□□□

7. □□□□□□□□□□

--	--	--	--	--

[illegible][illegible]

□□□□□□□□□□ISO9001

[illegible]

☐ OEM	☐	☐	☐	☐	☐
------------------------------	--------------------------	--------------------------	--------------------------	--------------------------	--------------------------