

Inspection Report

Report No.: XYL-150730
Supplier : XY-GLOBAL

Inspection Date: 14th Sep, 2015
Inspector: Leo

Inspection only for: PO : XYL-150730 Item No. XY11LM030	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM030	14000PCS	1% inspection	0pcs	No failure	14000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

[illegible]

Safety is our serious job for our worker and engineer team

