

Inspection Report

Report No.: XYSS-131010

Supplier: XY-GLOBAL

Inspection Date: 25th Nov., 2013

Inspector: LEO

Inspection only for: PO . XYSS-131010 Item No. Cylinder_FirstAid	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Cylinder_FirstAid	6PCS	100% inspection	0pcs	No failure	6pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 50pcs inspection.

Digital photo records :	
	
1. Packing	2. Packing
	
3. Product:	4. Product:
	
5. Product :	6. Product:

物料名称	铝合金 CNC 零件
规格	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
数量	10000
用途	机械零件
材质	AL6061
表面处理	阳极氧化
公差	±0.01
交货期	10 天
备注	客户要求提供材质证明
检验标准	ISO 9001
包装方式	纸箱
1.Name	铝合金 CNC 零件
2.Process	CNC 加工
3.规格	AL6061 AL6065 AL6063 AL7075
4.数量	10000
5.Tolerance	±0.01
6.交货期	10 天
7.Specification	ISO 9001
8.表面处理	阳极氧化
9.包装方式	纸箱
10.检验标准	Austrial
11.&NBSP;	ISO 9001
物料名称	铝合金 CNC 零件
1.规格	AL6061 AL6065 AL6063 AL7075
2.数量	10000
3.用途	机械零件
4.材质	AL6061
5.表面处理	阳极氧化
6.公差	±0.01
7.交货期	10 天
物料名称	铝合金 CNC 零件
1.规格	AL6061 AL6065 AL6063 AL7075
2.数量	10000
3.用途	机械零件
4.材质	AL6061
5.表面处理	阳极氧化
6.公差	±0.01
7.交货期	10 天