

Inspection Report

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYSL-130524 Item No. XY11SL014	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL014	8000PCS	5% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

[illegible]

6. The test report

11

[illegible]

1. 1000 000000000000
2. 0000 00000000000000000000
3. 00000000ADC12A3800
4. 00000000000000000000 0000
5. 00000000 ± 0.01 00
6. 00000000100000
7. 000000000000000000000000
8. 0000000025-3000
9. 00000000000000000000 0000000000000000
10. 00000000000000000000
11. 0000000000ISO 9001

00000

- 1.10 國際標準化組織
2. 國際標準化組織
3. 國際標準化組織
4. 國際標準化組織
5. 國際標準化組織
6. 國際標準化組織
7. 國際標準化組織

1111

[illegible][illegible]

ISO9001

[illegible]

OEM
