

Inspection Report

Report No.: XYSL-150603

Supplier : XY-GLOBAL

Inspection Date: 2th July, 2015

Inspector: Leo

Inspection only for:	<u>Inspection Result:</u>
PO . XYSL-150603 Item No. XY31XL002	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL002	22000PCS	1% inspection	Opes	No failure	22000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

podmínky		40000-1200	1.4.2018	3.4.
číslo	popis	částka	částka	částka
A	1.4.2018 - 3.4.			
1	40.000,00	40.000,00	40.000,00	40.000,00
2	1200,00	1200,00	1200,00	1200,00
3	1200,00	1200,00	1200,00	1200,00
4	1200,00	1200,00	1200,00	1200,00
B	1.4.2018 - 3.4.			
1	40.000,00	40.000,00	40.000,00	40.000,00
2	1200,00	1200,00	1200,00	1200,00
3	1200,00	1200,00	1200,00	1200,00
4	1200,00	1200,00	1200,00	1200,00
C	1.4.2018 - 3.4.			
1	40.000,00	40.000,00	40.000,00	40.000,00
2	1200,00	1200,00	1200,00	1200,00
3	1200,00	1200,00	1200,00	1200,00
4	1200,00	1200,00	1200,00	1200,00
D	1.4.2018 - 3.4.			
1	40.000,00	40.000,00	40.000,00	40.000,00
2	1200,00	1200,00	1200,00	1200,00
3	1200,00	1200,00	1200,00	1200,00
4	1200,00	1200,00	1200,00	1200,00
E	1.4.2018 - 3.4.			
1	40.000,00	40.000,00	40.000,00	40.000,00
2	1200,00	1200,00	1200,00	1200,00
3	1200,00	1200,00	1200,00	1200,00
4	1200,00	1200,00	1200,00	1200,00
F	1.4.2018 - 3.4.			
1	40.000,00	40.000,00	40.000,00	40.000,00
2	1200,00	1200,00	1200,00	1200,00
3	1200,00	1200,00	1200,00	1200,00
4	1200,00	1200,00	1200,00	1200,00
G	1.4.2018 - 3.4.			
1	40.000,00	40.000,00	40.000,00	40.000,00
2	1200,00	1200,00	1200,00	1200,00
3	1200,00	1200,00	1200,00	1200,00
4	1200,00	1200,00	1200,00	1200,00
H	1.4.2018 - 3.4.			
1	40.000,00	40.000,00	40.000,00	40.000,00
2	1200,00	1200,00	1200,00	1200,00
3	1200,00	1200,00	1200,00	1200,00
4	1200,00	1200,00	1200,00	1200,00
I	1.4.2018 - 3.4.			
1	40.000,00	40.000,00	40.000,00	40.000,00
2	1200,00	1200,00	1200,00	1200,00
3	1200,00	1200,00	1200,00	1200,00
4	1200,00	1200,00	1200,00	1200,00
J	1.4.2018 - 3.4.			
1	40.000,00	40.000,00	40.000,00	40.000,00
2	1200,00	1200,00	1200,00	1200,00
3	1200,00	1200,00	1200,00	1200,00
4	1200,00	1200,00	1200,00	1200,00

5. Product:

6. report

[illegible]

Safety is our serious job for our worker and engineer team

