

Inspection Report



Report No.: XYI-140314
Supplier : XY-GLOBAL

Inspection Date: 10th Apr, 2014
Inspector: Leo

Inspection only for: PO . XYI-140314 Item No.141030	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
141030	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	銅板銅箔OEM
品番	ADC12A380
単位	個
仕様	
材質	銅板銅箔
厚さ	0.01mm
寸法	CNC加工
表面処理	gague
公差	±0.01mm
公差	T / T 50
公差	20-25 NBSP
公差	ISO 9001
1.Name	銅板銅箔
2.Process	ADC12A380
4.公差	±0.01mm
5.Tolerance	100mm
6.公差	serice
7.Specification	25-30
8.公差	accessoried
9.公差	Austrial
10.公差	ISO 9001
11&NBSP;	ISO 9001
品名	
1.公差	ISO
2.公差	
3.公差	kindls
4.公差	available
5.公差	
6.公差	
7.公差	
品名	
公差	NBSP;
公差	
公差	ISO9001
公差	
公差	OEM