

Inspection Report

Report No.: XYDA-150307
Supplier: XY-GLOBAL

Inspection Date: 3th Apr, 2015
Inspector: Leo

Inspection only for: PO . XYDA-150307 Item No. XY31CY026	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY026	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.


Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

品名	铝合金CNC加工零件CNC件
材料	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
规格	定制
数量	1000个
单位	个
重量	约10kg
尺寸	长100mm 宽50mm 高20mm
表面处理	阳极氧化
公差	+/-0.01mm
交货期	5-7天
包装	泡沫箱+气泡膜
备注	请提供详细图纸
其他要求	无

1. CNC加工
2. 铝合金材料
AL6061 AL6065AL6063AL7075
4. 表面处理
5. 公差±0.01mm
6. 重量100g
7. 长度25-30mm
8. 宽度25-30mm
9. 高度25-30mm
10. 表面处理
11. ISO 9001
OEM加工
1. 10mm ISO
2. 10mm ISO
3. 10mm ISO
4. 10mm ISO
5. 10mm ISO
6. 10mm ISO
7. 10mm ISO
OEM加工
ISO9001
OEM加工
OEM加工