

Inspection Report

Report No.: XYL-150815
Supplier: XY-GLOBAL

Inspection Date: 23th Sep, 2015
Inspector: Leo

Inspection only for: PO: XYL-150815 Item No. XY11XL058	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11XL058	18000PCS	1% inspection	0pcs	No failure	18000pcs

Appearance Inspection:
No failure,
Dimension Inspection:
No failure, below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records:	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

[illegible]

High qualified surface treatment can make your parts perfect !!!

