

Inspection Report

Report No.: XYSL-150619
Supplier : XY-GLOBAL

Inspection Date: 25th July, 2015
Inspector: Leo

Inspection only for: PO . XYSL-150619 Item No. XY31XL017	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL017	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

pocdmis		MSD-01-108		J. B. 015	
NO.	DATE	TIME	DATE	TIME	NO.
1. 10-01					
1	10.01	10.01	10.01	10.01	10.01
2	10.02	10.02	10.02	10.02	10.02
3	10.03	10.03	10.03	10.03	10.03
4	10.04	10.04	10.04	10.04	10.04
2. 10-02					
1	10.05	10.05	10.05	10.05	10.05
2	10.06	10.06	10.06	10.06	10.06
3	10.07	10.07	10.07	10.07	10.07
4	10.08	10.08	10.08	10.08	10.08
3. 10-03					
1	10.09	10.09	10.09	10.09	10.09
2	10.10	10.10	10.10	10.10	10.10
3	10.11	10.11	10.11	10.11	10.11
4	10.12	10.12	10.12	10.12	10.12
4. 10-04					
1	10.13	10.13	10.13	10.13	10.13
2	10.14	10.14	10.14	10.14	10.14
3	10.15	10.15	10.15	10.15	10.15
4	10.16	10.16	10.16	10.16	10.16
5. 10-05					
1	10.17	10.17	10.17	10.17	10.17
2	10.18	10.18	10.18	10.18	10.18
3	10.19	10.19	10.19	10.19	10.19
4	10.20	10.20	10.20	10.20	10.20
6. 10-06					
1	10.21	10.21	10.21	10.21	10.21
2	10.22	10.22	10.22	10.22	10.22
3	10.23	10.23	10.23	10.23	10.23
4	10.24	10.24	10.24	10.24	10.24
7. 10-07					
1	10.25	10.25	10.25	10.25	10.25
2	10.26	10.26	10.26	10.26	10.26
3	10.27	10.27	10.27	10.27	10.27
4	10.28	10.28	10.28	10.28	10.28
8. 10-08					
1	10.29	10.29	10.29	10.29	10.29
2	10.30	10.30	10.30	10.30	10.30
3	10.31	10.31	10.31	10.31	10.31
4	10.32	10.32	10.32	10.32	10.32

6. report

[illegible]

Safety is our serious job for our worker and engineer team

