

# Inspection Report

Report No.: XYDK-130819

Supplier : XY-GLOBAL

Inspection Date:15<sup>th</sup> Sep-, 2013

Inspector:LEO

|                                    |                    |
|------------------------------------|--------------------|
| Inspection only for:               | Inspection Result: |
| PO . XYDK-130819    Item No.400379 | PASS               |

| Description | Finished Q'ty | Sample Size     | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|-----------------|--------------|---------------------|-----------------|
| 400379      | 500PCS        | 100% inspection | 0pcs         | No failure          | 500pcs          |

## Appearance Inspection :

No failure.

## Dimension Inspection:

No failure , below measurement report for reference.

## Assembly Test:

No failure

## Inspection Summary

The inspection sample plan is 100% inspection.

## Digital photo records :

|                                                                                     |  |                                                                                     |  |
|-------------------------------------------------------------------------------------|--|-------------------------------------------------------------------------------------|--|
|   |  |   |  |
| 1. Packing                                                                          |  | 2. Product:                                                                         |  |
|  |  |  |  |
| 3. Product:                                                                         |  | 4. Product:                                                                         |  |
|  |  |  |  |
| 5. Product :                                                                        |  | 6. Product:                                                                         |  |

[illegible]