

Inspection Report

Report No.: XYCY-150319
Supplier: XY-GLOBAL

Inspection Date: 15th Apr, 2015
Inspector: Leo

Inspection only for: PO: XYCY-150313 Item No. XY31CY021	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY021	55000PCS	1% inspection	0pcs	No failure	55000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure, below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

品名	汎用部品CNC加工品汎用部品CNC加工品
材質	材質 AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	仕様
数量	数量
単位	単位
公差	公差
表面処理	表面処理
検査	検査
納期	納期
価格	価格
備考	備考
1. 汎用部品CNC加工品	
2. 汎用部品CNC加工品	
汎用部品AL6061 AL6065AL6063AL7075	
4. 汎用部品CNC加工品 仕様	
5. 汎用部品±0.01mm	
6. 汎用部品100mm	
7. 汎用部品CNC加工品	
8. 汎用部品25-30mm	
9. 汎用部品CNC加工品 汎用部品CNC加工品	
10. 汎用部品CNC加工品	
11. 汎用部品ISO 9001	
汎用部品	
1.10 汎用部品ISO	
2. 汎用部品CNC加工品	
3. 汎用部品CNC加工品	
4. 汎用部品CNC加工品	
5. 汎用部品	
6. 汎用部品	
7. 汎用部品CNC加工品	
汎用部品	
汎用部品CNC加工品	
汎用部品CNC加工品	
汎用部品ISO9001	
汎用部品CNC加工品	
汎用OEM加工品	