

Inspection Report

Report No.: XYL-150803
Supplier : XY-GLOBAL

Inspection Date: 14th Sep, 2015
Inspector: Leo

Inspection only for: PO : XYL-150803 Item No. XY11LM033	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM033	16000PCS	1% inspection	0pcs	No failure	16000pcs

Appearance Inspection :
No failure,

Dimension Inspection:
No failure , below measurement report for reference.

Assembly Test:
No failure

Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing



2. Product



3. Product



4 Product



5. Product:

6. Report:

[illegible]

Safety is our serious job for our worker and engineer team

