

Inspection Report

Report No.: XYL-150722
Supplier: XY-GLOBAL

Inspection Date: 5th Sep, 2015
Inspector: Leo

Inspection only for: PO: XYL-150722 Item No. XY11LM022	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM022	16000PCS	1% inspection	0pcs	No failure	16000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure, below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

检查报告

品名	规格	数量	单位	检验日期	检验员
XY11LM022		16000	PCS	2015.09.05	Leo
检验项目	外观	尺寸	重量	性能	其他
检验结果	合格	合格	合格	合格	合格
检验结论	合格	合格	合格	合格	合格

6. Report:

	OEM
	ADC12A380
	+/-0.01
	5050
	5025
1.	
2.	
3.ADC12A380	
4.	
5. ± 0.01	
6.100	
7.	
8.25-30	
9.	
10.	
11.ISO 9001	
1.10ISO	
2.	
3.	
4.	
5.	
6.	
7.	
ISO9001	
OEM	

Safety is our serious job for our worker and engineer team

