XY-GLOBAL **XY Electronics Technology Co., Ltd**

Inspection Report

Report No.: XYWD-140630 **Inspection Date:** 28th July, 2014
Supplier : **XY-GLOBAL** **Inspector:** Leo

Inspection only for:	Inspection Result:
PO . XYWD-140630 Item No. XY31SY47	**PASS**

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY47	**90000PCS**	1% inspection	0pcs	No failure	90000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co.,Ltd

6. report

[illegible]	[illegible]CNC[illegible]CNC[illegible]
[illegible]	[illegible] AL6061 AL6065[illegible]AL6063[illegible]AL7075[illegible]SUS304[illegible]SUS303[illegible]SUS316[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible] [illegible]
[illegible]	[illegible] [illegible]
[illegible]	[illegible]
[illegible]/[illegible]	+/-0.01[illegible]
[illegible]	[illegible]50[illegible]50[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]50[illegible]25[illegible]
[illegible]	[illegible]

1.[illegible]CNC[illegible]
2.[illegible]
[illegible]AL6061 AL6065[illegible]AL6063[illegible]AL7075[illegible]
4.[illegible] [illegible]
5.[illegible]±0.01[illegible]
6.[illegible]100[illegible]
7.[illegible]
8.[illegible]25-30[illegible]
9.[illegible] [illegible]
10.[illegible]
11[illegible]ISO 9001
[illegible]
1.10[illegible]ISO[illegible]
2.[illegible]
3.[illegible]
4.[illegible]
5.[illegible]
6.[illegible]
7.[illegible]
[illegible]
[illegible]
[illegible]
[illegible]ISO9001
[illegible]
[illegible]OEM[illegible]