

Inspection Report

Report No.: XYS-130910
Supplier : XY-GLOBAL

Inspection Date: 25th Sep-, 2013
Inspector: LEO

Inspection only for: PO . XYS-130910 Item No. Accessories	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Accessories	5000PCS	5% inspection	0pcs	No failure	5000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 5% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

項目名	加工・組立CNC加工品CNC加工品
材料	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316
仕様	加工仕様
数量	数量単位 数量単位
単位	個
加工方法	CNC加工
加工条件	加工条件gague
加工条件	加工条件
公差	+/-0.01
公差	T / T 50T / T 50
公差	公差
公差	公差
公差	T / T 5020-25 NBSP
公差	公差
1.Name 加工cnc加工	
2.Process	
材料AL6061 AL6065AL6063AL7075	
4.加工条件	
5.Tolerance±0.01	
6.数量100	
7.Specificationserice	
8.数量25-30	
9.accessoried	
10.Austrial	
11 ISO 9001	
加工	
1.10ISO	
2.	
3.kindlsavailable	
4.	
5.	
6.	
7.	
加工	
加工	
加工	
ISO9001	
加工	
加工	