

Inspection Report

Report No.: XYL-150805
Supplier : XY-GLOBAL

Inspection Date: 14th Sep, 2015
Inspector: Leo

Inspection only for: PO : XYL-150805 Item No. XY11LM035	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM035	16000PCS	1% inspection	0pcs	No failure	16000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

検査報告									
検査項目	検査内容	検査結果	検査方法	検査場所	検査日時	検査者	検査機	検査用機	検査用材
1. 外形検査	外形寸法	OK	目視	工場	2015.09.14	Leo			
2. 機能検査	動作確認	OK	動作確認	工場	2015.09.14	Leo			
3. 電気特性検査	電圧・電流	OK	電圧・電流計	工場	2015.09.14	Leo			
4. 熱特性検査	発熱確認	OK	温度計	工場	2015.09.14	Leo			
5. 寿命試験	寿命試験	OK	寿命試験機	工場	2015.09.14	Leo			
6. 環境試験	環境試験	OK	環境試験機	工場	2015.09.14	Leo			
7. 信頼性試験	信頼性試験	OK	信頼性試験機	工場	2015.09.14	Leo			
8. 安全性試験	安全性試験	OK	安全性試験機	工場	2015.09.14	Leo			
9. 互換性試験	互換性試験	OK	互換性試験機	工場	2015.09.14	Leo			
10. 総合試験	総合試験	OK	総合試験機	工場	2015.09.14	Leo			

6. Report:

[illegible]

Safety is our serious job for our worker and engineer team

