XY-GLOBAL **XY Electronics Technology Co., Ltd**

# Inspection Report

**Report No.:** XYL-150724 **Inspection Date:** 12th Sep, 2015
**Supplier :** XY-GLOBAL **Inspector:** Leo

| Inspection only for: | Inspection Result: |
|---|---|
| PO . XYL-150724 Item No. XY11LM024 | PASS |

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|---|---|---|---|---|---|
| XY11LM024 | 18000PCS | 1% inspection | 0pcs | No failure | 18000pcs |

| Appearance Inspection : |
|---|
| No failure, |
| **Dimension Inspection:** |
| No failure , below measurement report for reference. |
| **Assembly Test:** |
| No failure |
| **Inspection Summary** |
| The inspection sample plan is 100% inspection. |

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

5. Product:

6. Report:

| | |
|---|---|
| □□□□ | □□□□

# Safety is our serious job for our worker and engineer team