

Inspection Report

Report No.: XYWD-140624
Supplier : XY-GLOBAL

Inspection Date: 20th July, 2014
Inspector: Leo

Inspection only for: PO : XYWD-140624 Item No. XY31SY41	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY41	80000PCS	1% inspection	0pcs	No failure	80000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Date: 2014.07.20	Product Type XY31SY41	Inspection Place XY Electronics Technology Co., Ltd
Inspector Leo	Inspector Leo	Inspector Leo

Inspection Result: **PASS**

Inspection Summary: No failure found.

Inspection Details:

Item	Quantity	Defect	Defect Description	Defect Count	Defect Rate
1	80000	0	No failure	0	0%

Inspection Conclusion: The inspection sample plan is 100% inspection.

5. Product:

6. report

[illegible]