

Inspection Report

Report No.: XYL-150803
Supplier : XY-GLOBAL

Inspection Date: 14th Sep, 2015
Inspector: Leo

Inspection only for: PO . XYL-150803 Item No. XY11XL046	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11XL046	14000PCS	1% inspection	Opcs	No failure	14000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product

[illegible]

5. Product:

6. Report:

項目	顧客指定の仕様書に準拠し、OEMの指示に従う。
部材	ADC12/A380
部材	標準品
数量	顧客指定の数量に準拠する。
単位	個
検査方法	目視・寸法測定・機能試験などを実施する。
検査項目	寸法公差・表面状態・動作確認などを行う。
検査結果	合格品と判定される。不良品は再工程へ送付される。
不良率	0.1%以下を目標とする。
納入期	+/-0.01日以内
ロット	最小ロット50個、最大ロット500個
梱包方法	ダンボール箱またはプラスチック容器で包装する。
保管場所	乾燥した室内に保管する。
有効期限	開封後50日間、未開封25日間
保証期間	製造日より1年
1. 品質管理の徹底	
2. 納期厳守の体制	
3. 顧客指定の仕様書に準拠	
4. 検出可能な不良品の発生	
5. 不良率±0.01%	
6. 出荷前100%検査	
7. 在庫管理の徹底	
8. 出荷前25-30分検査	
9. 顧客指定の仕様書に準拠	
10. 検出可能な不良品の発生	
11. ISO 9001認証取得	
品質管理	
1.10品質管理ISO	
2. 品質管理の徹底	
3. 品質管理の徹底	
4. 品質管理の徹底	
5. 品質管理	
6. 品質管理	
7. 品質管理の徹底	
品質管理	
品質管理の徹底	
品質管理の徹底	
品質管理ISO9001	
品質管理の徹底	
品質OEMの徹底	

High qualified surface treatment can make your parts perfect !!!

