

Inspection Report


Report No.: XYSS-130328
Supplier : XY-GLOBAL

Inspection Date: 9th Apr., 2013
Inspector: LEO

Inspection only for: PO . XYSS-130328 Item No. pressure modulation valve	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
pressure modulation valve	50PCS	100% inspection	0pcs	No failure	50pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Packing
	
3. Product:	4. Product:
	
5. Product :	6. Product:

	CNC
	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316
	&NBSP;
	gague
	T / T 50T / T
	20-25&NBSP; T / T 50
1.Name cnc	
2.Process	
4.	
5.Tolerance±0.01	
6.100	
7.Specificationserice	
825-30	
9accessoried	
10Austrial	
11&NBSP;ISO 9001	
110ISO	
2	
3kindlsavailable	
4	
5	
6	
7	
&NBSP;	
ISO9001	