

Inspection Report

Report No.: XYWD-140604
Supplier : XY-GLOBAL

Inspection Date: 2nd July, 2014
Inspector: Leo

Inspection only for: PO : XYWD-140604 Item No. XY31SY24	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY24	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.


Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing 	2. Product 
3. Product 	4 Product 
5. Product:	6. report 

[illegible]