

Inspection Report


Report No.: XYA-130507
Supplier : XY-GLOBAL

Inspection Date:12th Jun-, 2013
Inspector:LEO

Inspection only for: PO . XYA-130507 Item No. Spacer	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Spacer	1000PCS	50pcs inspection	0pcs	No failure	1000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 50pcs inspection.

Digital photo records :	
	
1. Packing	2. Packing
	
3. Product:	4. Product:
	
5. Product :	6. Product:

物料名称	铝棒 CNC 加工
规格	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
长度	1000mm
重量	0.0000kg
材质	AL6061
表面处理	阳极氧化
公差	±0.01mm
热处理	T / T 50
检验标准	ISO 9001
包装	1000mm
备注	
1.Name	铝棒 CNC 加工
2.Process	铝棒 CNC 加工
3.Specification	AL6061 AL6065 AL6063 AL7075
4.Tolerance	±0.01mm
5.Length	1000mm
6.Weight	0.0000kg
7.Specification	serice
8.Length	25-30mm
9.Specification	accessoried
10.Length	Austrial
11.Length	ISO 9001
12.Length	ISO 9001
13.Length	kindls available
14.Length	ISO 9001
15.Length	ISO 9001
16.Length	ISO 9001
17.Length	ISO 9001
18.Length	ISO 9001
19.Length	ISO 9001
20.Length	ISO 9001