



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYA-131021

Supplier : XY-GLOBAL

Inspection Date: 15th Nov-, 2013

Inspector: ALEX

Inspection only for: PO . XYA-131021 Item No. XY-CT-D-070	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-CT-D-065	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

	CNC CNC CNC
	AL6061 AL6065AL6063AL7075&NBSP; SUS304SUS303SUS316
	CNC
	gague
	+/-0.01
	T / T 50T / T
	T / T 5020-25 NBSP
1.Name cnc	
2.Process	
AL6061 AL6065AL6063AL7075	
4.	
5.Tolerance±0.01	
6.100	
7.Specificationserice	
8.25-30	
9.accessoried	
10.Austrial	
11&NBSP;ISO 9001	
1 10ISO	
2	
3kindlsavailable	
4	
5	
6	
7	
&NBSP;	
ISO9001	