

Inspection Report

Report No.: XYDA-140517

Inspection Date: 10th Jun, 2014

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYDA-140517 Item No.1464290	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1464290	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. Product:

