

Inspection Report


Report No.: XYN-140510
Supplier : XY-GLOBAL

Inspection Date: 7th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYN-140510 Item No.XY-140320	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-140320	40000PCS	1% inspection	0pcs	No failure	40000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	铝合金压铸件OEM
材料	ADC12/A380
数量	1000000
公差	±0.05
表面处理	阳极氧化
包装	散装
交货期	10天
付款方式	预付30%定金，余款货到后付清
备注	CNC加工
其他要求	符合RoHS标准，无铅
MOQ	1000
尺寸/重量	100x100x10mm / 10g
温度	T / T 50℃
表面处理	CNC加工，阳极氧化
其他要求	符合RoHS标准，无铅
包装	散装
交货期	10天
付款方式	预付30%定金，余款货到后付清
备注	CNC加工
其他要求	符合RoHS标准，无铅
1.Name	铝合金压铸件OEM
2.Process	CNC加工
3.	ADC12/A380
4.Surface	阳极氧化
5.Tolerance	±0.05
6.	1000000
7.Specification	OEM
8.	25-30天
9.	accessoried
10.	Austrial EU
11&NBSP	ISO 9001
品名	
ISO	1000000
2.	
3.sureface	finishment kinds available
品名	4.
5.	
品名	6.
7.	
品名	
品名	&NBSP
品名	
品名	ISO9001
品名	
OEM	