



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYK-130810

Supplier : XY-GLOBAL

Inspection Date:12th- Sep-, 2013

Inspector:LEO

Inspection only for:	<u>Inspection Result:</u>
PO . XYK-130810 Item No.1300420	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1300420	500PCS	3% inspection	0pcs	No failure	500pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure


Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing




2. Product:




3. Product:



4. Product:



5. Product :



6. Product:

	CNC CNC CNC CNC
	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316POM
	&NBSP
	CNC CNC
	gague
MOQ	
/	+/- 0.01
	T / T 5050T / T
	CNC CNC CNC CNC
	CNC
	20-25&NBSP T / T 50
	CNC
1.Name OEM CNC	
2.Process CNC	
3. AL6061 AL6065AL6063AL7075POM	
4.Surface nickle	
5.Tolerance +/- 0.01	
6 100	
7.Specification OEM	
8 25-30	
9 CNC accessoried	
10 Austrial EU	
11&NBSP ISO 9001	
ISO 110	
2	
3 sureface finishment kindls abailable	
4	
5	
6	
7	
CNC &NBSP	
CNC	
CNC ISO9001	
CNC	
CNC OEM	