



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYD-131017

Inspection Date: 15th Nov., 2013

Supplier : XY-GLOBAL

Inspector: ALEX

Inspection only for: PO : XYD-131017 Item No. XY-MST-080	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-MST-080	40000PCS	1% inspection	0pcs	No failure	40000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

	CNC 零件CNC零件CNC零件CNC零件CNC零件CNC零件CNC零件CNC零件CNC零件CNC零件
	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316POM
	CNC零件CNC零件CNC零件CNC零件CNC零件CNC零件CNC零件CNC零件CNC零件CNC零件
	gague
MOQ	
/mm	+/- 0.01mm
T / T	50T / T:
	CNC零件CNC零件CNC零件CNC零件CNC零件CNC零件CNC零件CNC零件CNC零件CNC零件
	20-25T / T 50
	CNC零件
1.Name	OEM CNC零件
2.Process	CNC零件
3.	AL6061 AL6065AL6063AL7075POM
4.Surface	nickle
5.Tolerance	+/- 0.01mm
6.	100%
7.Specification	OEM
8.	25-30%
9.	CNC零件accessoried
10.	AustrialEU
11&NBSP	ISO 9001
ISO	110
2.	
3.sureface	finishmentkindlsavailable
	4
5.	
	6
7.	
CNC	&NBSP
CNC	
CNC	ISO9001
CNC	
CNC	OEM