

**Inspection Report**

Report No.: XYD-140523  
 Supplier : XY-GLOBAL

Inspection Date: 15<sup>th</sup> Jun, 2014  
 Inspector: Leo

Inspection only for: PO . XYD-140523 Item No.5214001	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
5214001	6000PCS	1% inspection	0pcs	No failure	6000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

