

Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11KA001	18000PCS	5% inspection	0pcs	No failure	18000pcs

The inspection sample plan is 100% inspection.



2. Product



4 Product

[illegible]

6. The test report

[illegible]

Safety is our serious job for our worker and engineer team

