

Inspection Report


Report No.: XYK-140512
Supplier : XY-GLOBAL

Inspection Date: 9th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYK-140512 Item No.XY-140347	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-140347	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

ชื่อ	บริษัท อดิเรก จำกัด
ประเภท	ADC12 A380
ชื่อ	ชื่อ บริษัท
ชื่อ	ชื่อ บริษัท
ชื่อ	ชื่อ บริษัท
ชื่อ	CNC
ชื่อ	CNC
ชื่อ	ชื่อ บริษัท
MOQ	ชื่อ
ชื่อ/ชื่อ	+/- 0.01
ชื่อ	T / T 50
ชื่อ	CNC
ชื่อ	ชื่อ บริษัท
ชื่อ	ชื่อ บริษัท
ชื่อ	ชื่อ บริษัท
ชื่อ	20-25 T / T 50
ชื่อ	ชื่อ บริษัท
1.Name	ชื่อ บริษัท
2.Process	CNC
3.	ADC12 A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM
8.	25-30
9.	accessoried
10.	Austrial EU
11&NBSP	ISO 9001
ชื่อ	
ISO	1 10
2.	
3 sureface	finishment kinds available
ชื่อ	4
5.	
ชื่อ	6
7.	
ชื่อ	
ชื่อ	&NBSP
ชื่อ	
ชื่อ	ISO9001
ชื่อ	
OEM	