

AL 6061 CNC



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYK-130815

Supplier : XY-GLOBAL

Inspection Date:15th Sep-, 2013

Inspector:LEO

Inspection only for:	<u>Inspection Result:</u>
PO . XYK-130815 Item No.130478	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
130478	500PCS	3% inspection	0pcs	No failure	500pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:




3. Product:



4. Product:



5. Product :



6. Product:

[illegible]