

Inspection Report

Report No.: XYNK-130827

Supplier : XY-GLOBAL

Inspection Date:24th Sep-, 2013

Inspector:LEO

Inspection only for:	Inspection Result:
PO . XYNK-130827 Item No.1320779	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1320779	5000Pcs	100% inspection	0pcs	No failure	5000Pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.


Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing

2. Product:



3. Product:

4. Product:



5. Product :

6. Product:

[illegible]