

6061



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYA-130831&XYA-130901
Supplier : XY-GLOBAL

Inspection Date: 11th Sep-, 2013
Inspector: LEO

Inspection only for: PO . XYA-130831&XYA-130901 Item No.400-01-038/400-01-075	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-01-038	432PCS	7% inspection	0pcs	No failure	432pcs
400-01-075	150PCS	7% inspection	0pcs	No failure	150pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



PO:	343766 & 407163
QTY:	400-01-038 432PCS 400-01-075 150PCS
G.W:	20.5 KGS
MEAS:	28 X 28 X 24 CM



1. Packing

2. Packing



3. Product: 400-01-075

4. Product: 400-01-075



5. Product : 400-01-075

6. Product: 400-01-075

[illegible]