

Inspection Report

Report No.: XYAN-150405

Supplier : XY-GLOBAL

Inspection Date: 5th May-, 2015

Inspector: LEO

Inspection only for:	Inspection Result:
PO : XYAN-150405 Item No. XY21ZC073	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC073	8000pcs	7% inspection	0pcs	No failure	8000pcs

Appearance Inspection :
No failure,

Dimension Inspection:
No failure , below measurement report for reference.

Assembly Test:
No failure

Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing




2. Product:



3. Product:



4. Product:



5. Product :

6. Inspection report:

[illegible]

Safety is our serious job for our worker and engineer team

