



**Inspection Report**







**Report No.:** XYS-130914  
**Supplier :** XY-GLOBAL

**Inspection Date:** 11<sup>th</sup> Oct, 2013  
**Inspector:** Leo

Inspection only for: PO . XYS-130920 Item No.3567200	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
3567200	3000PCS	5% inspection	0pcs	No failure	3000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

ชื่อ	บริษัท ออโต้แมค จำกัด OEM
ประเภท	ADC12 A380
วัสดุ	อลูมิเนียม
ขนาด	ตามแบบร่าง
กระบวนการ	CNC
MOQ	1000
ความแม่นยำ	+/- 0.01
ระยะเวลา	T / T 50% T / T
สถานที่	CNC
การรับประกัน	ตามเงื่อนไข
ราคา	20-25 T / T 50%
ข้อกำหนด	ตามแบบร่าง
1.Name	บริษัท ออโต้แมค จำกัด
2.Process	CNC
3.วัสดุ	ADC12 A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.ขนาด	100
7.Specification	OEM
8.ระยะเวลา	25-30
9.การรับประกัน	accessoried
10.มาตรฐาน	Austrial EU
11.&NBSP	ISO 9001
ISO	1 10
2.	
3.sureface	finishment kinds available
4.	
5.	
6.	
7.	
ISO	
&NBSP	
ISO	9001
OEM	