

Inspection Report

Report No.: XYKI-140302
Supplier : XY-GLOBAL

Inspection Date: 7th Apr, 2014
Inspector: Leo

Inspection only for: PO . XYKI-140302 Item No.1900031	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1900031	6000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

Company Name	Shenzhen Hengsheng Technology Co., Ltd. OEM/ODM service available
Product Name	ADC12/A380
Material	Aluminum
Surface Treatment	Anodizing / Electroplating
Process	CNC Machining
MOQ	1000
Lead Time	15-20 days
Payment Terms	T/T, L/C, Western Union
Quality Control	ISO 9001:2015
Shipping Method	By Air / By Sea
1. Name	Shenzhen Hengsheng Technology Co., Ltd. OEM/ODM service available
2. Process	CNC Machining
3. Material	Aluminum ADC12/A380
4. Surface	Anodizing / Electroplating
5. Tolerance	±0.01mm
6. Quantity	1000
7. Specification	OEM/ODM service available
8. Lead Time	15-20 days
9. Accessory	Accessories available
10. Certification	Australia / EU
11. ISO 9001	ISO 9001:2015
ISO 9001	ISO 9001:2015
2. Quantity	1000
3. Surface Finish	Kind of finish available
4. Price	
5. Lead Time	
6. Quantity	
7. Specification	
8. Lead Time	
9. Accessory	
10. Certification	ISO 9001
11. ISO 9001	
OEM/ODM	