

Inspection Report

Report No.: XYKI-140316
Supplier : XY-GLOBAL

Inspection Date: 15th Apr, 2014
Inspector: Leo

Inspection only for: PO . XYKI-140316 Item No.140093	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
140093	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

Company Name	Shenzhen Hengsheng Technology Co., Ltd. OEM/ODM service available
Product Name	ADC12/A380
Material	Aluminum
Surface Treatment	Anodizing / Powder Coating / Electroplating
Process	CNC Machining
MOQ	1000
Lead Time	15-20 days
Payment Terms	T/T, L/C, Western Union
Quality Control	ISO 9001:2015
Shipping Method	By Air / By Sea
1. Name	Shenzhen Hengsheng Technology Co., Ltd. OEM/ODM service available
2. Process	CNC Machining
3. Material	Aluminum ADC12/A380
4. Surface	Anodizing / Powder Coating / Electroplating
5. Tolerance	±0.01mm
6. Quantity	1000
7. Specification	OEM/ODM service available
8. Lead Time	15-20 days
9. Accessory	Accessories available
10. Certification	Australia / EU
11. ISO 9001	ISO 9001:2015
12. ISO 10	ISO 10
13. Sureface	finishment kinds available
14. Price	
15. Weight	
16. Size	
17. Material	
18. Quality Control	ISO 9001:2015
19. Shipping Method	By Air / By Sea
20. OEM/ODM	OEM/ODM service available