

Inspection Report

Report No.: XYBA-140927

Supplier : XY-GLOBAL

Inspection Date: 27th Oct-, 2014

Inspector:LEO

Inspection only for:	<u>Inspection Result:</u>
PO . XYBA-140927 Item No. XY21ZC019	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC019	3800pcs	7% inspection	0pcs	No failure	3800pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:

[illegible]

6. Inspection report:

[illegible]