

□□□□□□□□□□□□□□□□6061□□□□□□□□□□□□

Inspection Report

Report No.: XYS-130511
Supplier : XY-GLOBAL

Inspection Date: 04th Jun, 2013
Inspector: Leo

Inspection only for: PO . XYS-130511 Item No.XY-130101	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-130101	1000PCS	5% inspection	0pcs	No failure	1000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

	OEM
ADC12A380	
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50T / T
	CNC
	20-25T / T 50
1.NameOEM	
2.ProcessCNC	
3.ADC12A380	
4.Surfacenickle	
5.Tolerance+/- 0.01	
6.100	
7.SpecificationOEM	
8.25-30	
9.accessoried	
10.AustrialEU	
11&NBSPISO 9001	
1 ISO10	
2	
3 surefacefinishmentkindlsavailable	
4	
5	
6	
7	
&NBSP	
ISO9001	
OEM	