

Inspection Report

Report No.: XYN-130822

Inspection Date: 14th Sep, 2013

Supplier : XY-GLOBAL

Inspector: LEO

Inspection only for: PO : XYN-130822 Item No. 1402310	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1402310	2000PCS	1% inspection	0pcs	No failure	2000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

	CNC
	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316POM
	CNC
	gague
MOQ	
	+/- 0.01
	T / T 50 T / T;
	CNC CNC CNC CNC
	CNC
	20-25 T / T 50
	CNC
1.Name OEM CNC	
2.ProcessCNC	
3.AL6061 AL6065AL6063AL7075POM	
4.Surfacenickle	
5.Tolerance+/- 0.01	
6100	
7.SpecificationOEM	
825-30	
9CNCaccessoried	
10AustrialEU	
11 ISO 9001	
ISO110	
2	
3 surefacefinishmentkindlsavailable	
4	
5	
6	
7	
CNC&NBSP	
CNC	
CNCISO9001	
CNC	
CNCOEM	