

Inspection Report

Report No.: XYBA-141124
 Supplier : XY-GLOBAL

Inspection Date: 19th Dec-, 2014
 Inspector:LEO

Inspection only for: PO . XYBA-141124 Item No. XY21ZC042	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC042	5000Pcs	7% inspection	0pcs	No failure	6000Pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

製品名	CNC 製品名 CNC製品名 CNC製品名 CNC製品名 CNC製品名 CNC製品名 CNC製品名 CNC製品名
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
仕様	
表面処理	表面処理 表面処理 表面処理 表面処理
公差	CNC 公差 CNC 公差 CNC 公差 CNC 公差 CNC 公差
MOQ	
許容公差	+/- 0.01
納期	T / T 50% 50% T / T; 納期
加工	CNC 加工 CNC 加工 CNC 加工 CNC 加工 CNC 加工 CNC 加工 CNC 加工
品質管理	品質管理 品質管理 品質管理 品質管理 品質管理 品質管理 品質管理 品質管理
検査	
納期	20-25 T / T 50%
加工	CNC 加工
1.Name	OEM CNC
2.Process	CNC
3.Material	AL6061 AL6065 AL6063 AL7075 POM
4.Surface	nickle
5.Tolerance	+/- 0.01
6. MOQ	100
7.Specification	OEM service
8. 納期	25 30
9. 加工	CNC 加工 accessoried
10. 品質	Austrial EU
11. 検査	ISO 9001
ISO 9001	
ISO 10	
3. surface finishment	kindls available
4. 納期	
5. 品質	
6. 検査	
7. 加工	
品質	
CNC 加工	
CNC 加工	
CNC 加工	ISO9001
CNC 加工	
CNC 加工	OEM